

● PRINTER RUSH ●
(PTO ASSISTANCE)

Application :	<u>09/74/129</u>	Examiner :	<u>Hannett</u>	GAU :	<u>2612</u>	
From:	<u>N/93</u>	Location:	<u>(IDC) FMF FDC</u>	Date:	<u>8-1-05</u>	
Tracking #:			<u>06117308</u>	Week Date:		<u>0-13-05</u>

DOC CODE	DOC DATE	MISCELLANEOUS
<input type="checkbox"/> 1449	_____	<input type="checkbox"/> Continuing Data
<input type="checkbox"/> IDS	_____	<input type="checkbox"/> Foreign Priority
<input type="checkbox"/> CLM	_____	<input type="checkbox"/> Document Legibility
<input type="checkbox"/> IIFW	_____	<input type="checkbox"/> Fees
<input type="checkbox"/> SREW	_____	<input type="checkbox"/> Other
<input checked="" type="checkbox"/> DRW	<u>12/19/2000</u>	
<input type="checkbox"/> OATH	_____	
<input type="checkbox"/> 312	_____	
<input type="checkbox"/> SPEC	_____	

[RUSH] MESSAGE: Attn: Chief Draftsperson

Drawing pages 1-10 have lines through drawings
caused by a flaw in the copying process.

Mark Goy
N/93

[XRUSH] RESPONSE: _____

DRAWINGS CORRECTED

8-4-2005

INITIALS: 157

NOTE: This form will be included as part of the official USPTO record, with the Response document coded as XRUSH.
REV 10/04








Fig. 5






Fig. 6

FIG. 7

Fig. 7




Fig. 10

